

JUDGE STEVE HERRERA JUDICIAL COMPLEX SANTA FE, NEW MEXICO

Status for the Week of June 20, 2011

During the week of June 20, the following events took place. Rebar, formwork, and concrete pours for the lower level interior walls; electrical conduit in the lower level interior walls; rebar for columns at upper level grade beams; and backfill for the lower basement ramp.

Schedule for the Week of June 27, 2011

The schedule for the week of June 27 will include the following events: Waterproof liner for interior wall at west end of lower level; continued formwork for deck at lower level; continued backfill of ramp at lower level; and rough-in of mechanical and electrical at post-tension deck.



Formwork continued on inner southwest wall of lower level



Rebar and formwork for walls at lower level for elevator, stairs, and mechanical rooms



Formwork started on inner northwest wall of lower level



Backfill of ramp at lower level east



Formwork started for deck at parking structure



Forms for interior walls and deck at parking structure

This report was prepared by Sherry Keefe.

OWNER'S REPRESENTATIVE:
Gerald A. Martin, Ltd.



Sherry Keefe